

101 816799

10/1



DOCKET NO.: STMI08-00007

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No. : 7,159,199 B2

Inventor(s) : Robert Warren

Issued : January 2, 2007

Title : METHOD FOR VERIFYING ADEQUATE SYNCHRONIZATION
OF SIGNALS THAT CROSS CLOCK ENVIRONMENTS AND
SYSTEM

Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
APR 11 2007
of Correction

CERTIFICATE OF MAILING BY FIRST CLASS MAIL

Sir:

The undersigned hereby certifies that the following documents:

1. Request for Certificate of Correction (in duplicate);
2. Certificate of Correction (in duplicate); and
3. A postcard receipt

relating to the above application, were deposited as "First Class Mail" with the United States Postal Service, addressed to Certificate of Correction Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on April 5, 2007.

Date: April 5, 2007 Kathy Hamilton
Mailer


Date: March 30, 2007 William A. Munck
William A. Munck
Reg. No. 39,308

P.O. Box 802432
Dallas, Texas 75380
Phone: (972) 628-3600
Fax: (972) 628-3616
E-mail: wmunck@munckbutrus.com

APR 11 2007

DOCKET NO.: STM108-00007

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No. : 7,159,199 B2
Inventor(s) : Robert Warren
Issued : January 2, 2007
Title : METHOD FOR VERIFYING ADEQUATE SYNCHRONIZATION
OF SIGNALS THAT CROSS CLOCK ENVIRONMENTS AND
SYSTEM

Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION

Certain clerical or typographical errors were noted in the above-identified patent as indicated on the attached Certificate of Correction.

Applicant respectfully requests that a Certificate of Correction be issued pursuant to 37 C.F.R. §1.322. It is believed that this error is the office's mistake and therefore no fee is due. If this is incorrect, the Commissioner is hereby authorized to charge any additional fee associated with this communication or credit any overpayment to Deposit Account Number 50-0208.

APR 11 2007

ATTORNEY DOCKET NO.: STMI08-00007
PATENT NO.: 7,159,199 B2

Respectfully submitted,

MUNCK BUTRUS, P.C.

Date: March 30, 2007




William A. Munck
Registration No. 39,308

P.O. Box 802432
Dallas, Texas 75380
Telephone: (972) 628-3600
Facsimile: (972) 628-3616
E-mail: wmunck@munckbutrus.com

DUPLICATE

DOCKET NO.: STMI08-00007

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No. : 7,159,199 B2
Inventor(s) : Robert Warren
Issued : January 2, 2007
Title : METHOD FOR VERIFYING ADEQUATE SYNCHRONIZATION
OF SIGNALS THAT CROSS CLOCK ENVIRONMENTS AND
SYSTEM

Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION

Certain clerical or typographical errors were noted in the above-identified patent as indicated on the attached Certificate of Correction.

Applicant respectfully requests that a Certificate of Correction be issued pursuant to 37 C.F.R. §1.322. It is believed that this error is the office's mistake and therefore no fee is due. If this is incorrect, the Commissioner is hereby authorized to charge any additional fee associated with this communication or credit any overpayment to Deposit Account Number 50-0208.

DUPLICATE

APR 11 2007


DUPLICATE

ATTORNEY DOCKET No.: STMI08-00007
PATENT No.: 7,159,199 B2

Respectfully submitted,

MUNCK BUTRUS, P.C.

Date: March 30, 2007



William A. Munck
Registration No. 39,308

P.O. Box 802432
Dallas, Texas 75380
Telephone: (972) 628-3600
Facsimile: (972) 628-3616
E-mail: wmunck@munckbutrus.com

DUPLICATE

APR 11 2007

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,159,199 B2
DATED : January 2, 2007
INVENTOR(S) : Robert Warren

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4, line 61, delete "if" and replace with -- 1f --;

Column 8, claim 1, line 64, insert -- plurality of -- before the term "functional" and delete "plurality of" after the term "elements".

MAILING ADDRESS OF SENDER:
Docket Clerk
P.O. Box 802432
Dallas, Texas 75380

PATENT NO. 7,159,199 B1

No. of additional copies

⇒ 1

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

APR 11 2007

DUPLICATE

PTO/SB/44 (04-04)

Approved for use through 04/30/2007. OMB 0651-0033

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,159,199 B2

DATED : January 2, 2007

INVENTOR(S) : Robert Warren

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4, line 61, delete "if" and replace with -- 1f --;

Column 8, claim 1, line 64, insert -- plurality of -- before the term "functional" and delete "plurality of" after the term "elements".

MAILING ADDRESS OF SENDER:

Docket Clerk
P.O. Box 802432
Dallas, Texas 75380

PATENT NO. 7,159,199 B1

No. of additional copies

⇒ 1

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

DUPLICATE